


Presentation Cart

AV Cart w/Adjustable Height Shelf



Assembly Instructions

Presentation Cart

AV Cart w/Adjustable Height Shelf


| Part | Drawing | Description | Qty | Part | Draw | ing | Description | Qty |
|--|-------------|--------------------|------|---|------|-------|---------------------|-------|
| P1 | | Leg Assembly Right | 1 EA | P-9 | | | Right Shelf Bracket | 1 EA |
| P2 | | Leg Assembly Left | 1 EA | P-1 | 10 | 0 | Left Shelf Bracket | 1 EA |
| | | | | | | Н | ardware List | |
| P3 | | LCD Platform | 1 EA | А | | 9/16 | "Socket Screw | 22 EA |
| P4 | | Laptop Shelf | 1 EA | В | | 2-1/2 | 2" Socket Screw | 4 EA |
| | | | | С | | Squa | re Nut | 4 EA |
| P5 | | Lower Shelf | 1 EA | D-1 | | 3" Lo | cking Caster | 2 EA |
| P6 | | Middle Shelf | 1 EA | D-2 | | 3" Ca | aster | 2 EA |
| P7 | | Stability Panel | 1 EA | E | | Plast | ic Grommet | 2 EA |
| P8 | | Angle Bracket | 4 EA | F | | Aller | n Wrench | 1 EA |
| | | | | G | | Cast | er Wrench | 1 EA |
| | | | | | | | | |
| Missing Parts or UPS Damaged Parts For Your Convenience you can EMAIL us at furniture @baltinc.com 24HOURS 7 DAYS A WEEK | | | | We recommend that you assemble this unit on a table. Tools required: Adjustable Crescent Wrench | | | | |
| | 24HOURS / L | DAYS A WEEK | | 10015 required. Adjustable Crescent Wienen | | | | |


Do not use unless all screws are tight. At least every six months, check all screws to be sure they are tight. If parts are missing, broken, damaged, or worn, stop use of the product until repairs are made by your dealer using factory authorized parts.


Presentation Cart Assembly Diagram

READ THROUGH INSTRUCTIONS FROM BEGINNING TO END <u>BEFORE</u> STARTING TO ASSEMBLE UNIT.


- 1.) Identify and Separate all the Parts and Hardware.
- 2.) Place the LCD Platform (P-3) with the insert nuts facing up. Attach 1 Right Leg Assembly (P-1) and 1 Left Leg Assembly (P-2) using 4 each (A) screws. (Finger tighten only)








6.) Attach Lower Shelf (P-5) to the Right & Left Leg Assemblies (P1 & P2) using 4 each (B) screws as shown in illustration # 4.



- 8.) Slide Middle Shelf (P-6) Between Right & Left Leg Assemblies (P-1 & P-2) and attach Middle Shelf (P-6) using 4 each (A) screws and 4 each (C) Square Nuts as shown in illustration # 4. Secure Middle Shelf (P-6) to Stability Panel (P-7) using two screws (A).
- 9.) (Tighten all the screws at this time using Allen Wrench (F)).

10.) To install Grommets (E) in LCD Platform (P-3) and Middle Shelf (P-6), separate parts and press Grommet Sleeve in rectangular openings as shown in illustration # 5.



The Balt product you have purchased is guaranteed against material and workmanship defects. This guarantee extends 1 year from date of purchase. Should this product fail to function satisfactorily under normal use due to defect or imperfection, the defective part or product will be replaced. Damage caused by common carriers during shipment is not included in this guarantee.

This guarantee sets forth all applicable guarantees and remedies. No other warranty, expressed or implied shall apply. Failure to follow instructions found in Important Information Section of Owner Sheet shall void the guarantee. Consequential or incidental damages and or costs are not refundable.

#66450 4 Outlet Electrical Assembly Diagram


This 4 Outlet Electrical is Part # 66450 and must be purchased separately. Please contact our Customer Service Department Monday - Friday 8 a.m. - 5 p.m. Central Standard Time 1-800-749-2258 Parts/Hardware List

EL-1 Electric Outlet 1 EA

EL-2 Metal Bracket w/Cord Winder 1 EA

EL-3 Phillips Head Screw 2 EA

EL-4 Hex Nut 2 EA



#66572 7 Outlet Electrical **Assembly Diagram**

This 7 Outlet electrical is Part # 66572 and must be purchased separately. Please contact our **Customer Service Department** Monday - Friday 8 a.m. - 5 p.m. **Central Standard Time** 1-800-749-2258

Parts/Hardware List 7 Outlet Electrical 1 EA Metal Bracket w/Cord Winder 1 EA EL-3 Phillips Head Screw 2 EA EL-4 Hex Nut 2 EA

1.) Identify and Separate all the Parts and Hardware.

2.) Slide Metal Bracket over the Electrical Outlet (EL-1) as shown. (note that Metal Stop is at the end with the electrical Plug-in.)

3.) Attach Metal Bracket (EL-2) to the Right or Left Leg Assembly (P-1 or P-2) using 2 Phillips Head Screws (EL-3) and 2 Hex Nuts (EL-4) as shown in Optional Electrical illustration.

Stop

Optional Electrical Illustration

